


SUPPORTING INFORMATION

PHOTOGRAPHY DOCUMENTING INVESTIGATIVE WORKS TO EXISTING FLOOR / CEILING AND JOIST POSITION



EXISTING FLOOR FINISH:

35MM ENGINEERED TIMBER BOARDS
GLUED TO CHIPBOARD, SITTING ON MDF BOARDS.

ENGINEERED TIMBER PLANKS HAVE BEEN RETAINED
FOR RE-USE IN ORDER TO MAKE AREA GOOD POST
DUCTWORK INSTALLATION.

EXISTING FLOOR FINISH:


BENEATH MDF BOARDS SIT ACOUSTIC INSULATION
BLANKET, FOLLOWED BY A VOID FILLED IN PART
WITH INSULATION.

JOISTS EXPOSED.



SUPPORTING INFORMATION

PHOTOGRAPHY DOCUMENTING INVESTIGATIVE WORKS TO EXISTING FLOOR / CEILING AND JOIST POSITION



EXISTING CEILING FINISH BELOW:

PLASTERBOARD.
(NO LATH & PLASTER PRESENT)



JOISTS LOCATION

VOID WILL NOT REQUIRE ANY STRUCTURAL CHANGES.
DUCTWORK TO BE SPLIT IN TWO SECTIONS TO PASS BETWEEN EXISTING JOISTS, AND RE-CONNECTED TO A HEADER DUCT.

DUCTWORK WILL BE BESPOKE MANUFACTURED AND SIZED TO SUIT THE DISTANCE BETWEEN THE EXISTING JOISTS, TO AVOID ANY CUTTING OR TRIMMING.



SUPPORTING INFORMATION

PHOTOGRAPHY DOCUMENTING INVESTIGATIVE WORKS TO EXISTING
FLOOR / CEILING AND JOIST POSITION



**EXISTING DUCTWORK AND CANOPY POSITION
IN KITCHEN AREA BELOW**

NEW PROPOSAL WILL NOT EFFECT EXISTING
POSITION OF CANOPY AND AREA WILL BE MADE
GOOD AND FIT FOR PURPOSE.



**EXISTING DUCTWORK POSITION
IN KITCHEN AREA BELOW**

EXISTING DUCTWORK EXITS VIA EXISTING WINDOW
APERTURE.

EXISTING WINDOW WAS REMOVED IN PART AND
HAS BEEN RETAINED, TO BE RE-INSTALLED AND
MADE GOOD AS PART OF PROPOSED WORKS.

