

Ref: LBC/19/00686 – TSD09

Date: 21/08/2025

MATERIAL SAMPLES CONDITION: CONDITION 2 APPLICATION – SHIREHALL REF: LBC/2019/00686

Please find below photographs taken of the samples of materials proposed for the REPLACEMENT of cleaved / cracked / holed BRICKS (yellow imperial stock), on selected areas to North (rear) and East (left side) facade at the above applicant site:



Plate 1: Existing stone face delaminations
Marked with chalk and templated for replacement



Plate 2: Witton Fell quarry, Buff sandstone
matched to pieces of existing fallen stone at
Shirehall.



Plate 3: Cutting out defective stones



Plate 4: New stone arrived ready for carving




Plate 5: Cutting out defective stone (pediment 3)
Templating completed for new stone order.




Plate 6: Benchmarking document for
replacement stone approval.

Cleaved, split / holed or defective YELLOW STOCK BRICKS (North and East elevations) of Shirehall are to be replaced using new Witton Fell Quarry Buff sandstone slips (min 50mm thick), pinned with stainless steel rods to existing good stone, bedded on lime mortar with Blaenavon dark lime pointing over to exactly match existing BRICKS in type, colour, dimensions and fit.

A total of 130 yellow stock imperial Bricks have been identified as defective – they require BRICK replacements in like for like stock reclaimed bricks.

