

Ref: LBC/19/00686 – TSD13
Date: 08/09/2025



MATERIAL SAMPLES CONDITION: CONDITION 2 APPLICATION – SHIREHALL REF: LBC/2019/00686

Please find below photographs taken of the samples of materials proposed for the REPLACEMENT of cracked or missing PUTTIES within sash and casement windows (matched exactly to existing), on selected windows to the facades at the above applicant site:



Plate 1: Broken / missing existing putties



Plate 2: New LINSEED oil traditional putty



Plate 3: On site fitted and new putties applied



Plate 4: Decorations applied following drying

Cracked or missing GLAZING PUTTY (all elevations) of Shirehall are to be replaced using traditional linseed oil putty - to exactly match existing in specification, dimensions and fit. All sound original putty remains.

