




Warning: PDF designed for A3 colour print only with no page scaling

Contact Us
Mapping Enquiries: 02920 278 912
General Enquiries: 0800 912 2999

Date Requested: 09/01/2026
Job Reference: 40009148
Site Location: 337216 187027
Requested by:
Mr Geraint Roberts
Your Scheme/Reference:
25/1001

Scale: 1:2563 (When plotted at A3)

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 278912

Dig Sites

Area: 

Line: 



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Line/Fire Valve



Governor Station



Change of Diameter



End Cap



Depth of cover



WALES&WEST
UTILITIES



Smell gas?
Call the Gas Emergency Service on
0800 111 999.



Dial
before
you dig



Investigate
Before you dig, make sure
you know what's below.




Go ahead
Done your research?
Now you can dig safely.



We need
10 days'
notice

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2025. All rights reserved. Ordnance Survey Licence number 0100044308.



Contact Us
Mapping Enquiries: 02920 278 912
General Enquiries: 0800 912 2999

Date Requested: 09/01/2026
Job Reference: 40009148
Site Location: 337216 187027
Requested by:
Mr Geraint Roberts
Your Scheme/Reference: 25/1001

Scale: 1:1250 (When plotted at A3)

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 278912

In case of an emergency call 0800 111 999

Dig Sites

Area: 

Line: 



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Line/Fire Valve



Governor Station



Change of Diameter



End Cap



Depth of cover





We need 10 days' notice



Smell gas?
Call the Gas Emergency Service on
0800 111 999.



Dial

before you dig



Investigate


Before you dig, make sure
you know what's below.



Go ahead

Done your research?
Now you can dig safely.

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2025. All rights reserved. Ordnance Survey Licence number 0100044308.



Warning: PDF designed for A3 colour print only with no page scaling

Contact Us Mapping Enquiries: 02920 278 912 General Enquiries: 0800 912 2999 Date Requested: 09/01/2026 Job Reference: 40009148 Site Location: 337216 187027 Requested by: Mr Geraint Roberts Your Scheme/Reference: 25/1001 Scale: 1:1250 (When plotted at A3) IMPORTANT NOTICES - This information is given as a guide only and its accuracy cannot be guaranteed - The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter - Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated - You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used - It is your responsibility to ensure this information is provided to all persons working near our plant - If in doubt call the WWU dig team on 02920 278912 In case of an emergency call 0800 111 999 Dig Sites Low Pressure (LP) 21mbar – 75mbar Medium Pressure (MP) 350mbar – 2bar Intermediate Pressure (IP) 2bar – 7bar High Pressure (HP) >7bar Area: Line: Line/Fire Valve Governor Station Change of Diameter End Cap Depth of cover WALES&WEST UTILITIES Dial before you dig We need 10 days' notice Smell gas? Call the Gas Emergency Service on 0800 111 999. Dial before you start work. Call 029 2027 8912 Investigate Before you dig, make sure you know what's below. Go ahead Done your research? Now you can dig safely. Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2025. All rights reserved. Ordnance Survey Licence number 0100044308.
--