

GENERAL NOTES

This drawing should be read in conjunction with the supporting documents submitted with this application.

In particular, for a detailed description of the proposals, specific reference should be made to 'Section 6: The Proposals' in the accompanying Heritage Impact Assessment along with 'Section 3.8: Design Development and Proposals' within the accompanying Design and Access Statement.

NOTES

1. Mechanical extract vents to be finished externally with Cast Iron Heritage Vent from the Cast Iron Air Brick Company, or similar approved.
2. Stainless steel flue to internal multi-fuel burner with insulated rain cap designed by specialist. All components externally, including connections, terminals and brackets to be powder coated in colour pack to match existing rainwater goods and decorative ironwork generally.
3. A number of existing windows incorporate glaze vents set within existing diamond quames with copper tube drain to the side of the window. Where these are not present to windows (replaced), 2 no existing diamond quames to be replaced with glaze (one at top, one at bottom) within glazed lights to enable natural ventilation to secondary glazing void with copper drain tube to base of window, all to match existing glaze locations present at the church.

