

Photographic record – Rainwater goods removal, temporary provisions – Easter holidays 2025



Existing rainwater goods



Blocked down pipe causing over spill and damp walls



Downpipe off courtyard



Rain water goods off store room



Rainwater goods to rear of school house



Blocked gully to side / rear elevation to be reviewed further.



Rainwater goods to rear of school house



Blocked gully – to be reviewed



Gutters replaced – temporary provisions – downpipe remains in place will be treated in-situ



Gutters replaced – temporary provisions



Temporary provisions - gutters



Gutters and downpipe removed – temporary rainwater goods



Gutters and downpipe removed – temporary rainwater goods



Temporary rainwater goods



Temporary rainwater goods



Partial removal – original hopper and bend was completely blocked with debris



Downpipe remains due to unusual fixings – to be treated on site.



Temporary rainwater goods



Temporary rainwater goods