

Ref: LBC/19/00686 – TSD08

Date: 20/09/2025

MATERIAL SAMPLES CONDITION: CONDITION 2 APPLICATION – SHIREHALL REF: LBC/2019/00686

Please find below photographs taken of the samples of materials proposed for the REPAIR of glazed ceramic BRICKS on THE REAR LIGHTWELL elevations at the above applicant site:



Plate 1: Holed / cracked Ceramic Bricks



Plate 2: repaired and repointed ceramic brick



Plate 3 & 4: Application of off white polyester resin repair to ceramic bricks on site