

Ref: LBC/19/00686 – TSD12
Date: 05/09/2025



MATERIAL SAMPLES CONDITION: CONDITION 2 APPLICATION – SHIREHALL REF: LBC/2019/00686

Please find below photographs taken of the samples of materials proposed for the REPLACEMENT of cracked or broken glazing within sash and casement windows (matched exactly to existing), on selected windows to the facades at the above applicant site:



Plate 1: Broken / cracked existing windows



Plate 2: New glass cylinder drawn



Plate 3: Replacement glazing pane



Plate 4: On site fitted and new putties to hold

Cracked or broken GLASS WINDOWS (all elevations) of Shirehall are to be replaced using matched glass - to exactly match existing BROKEN PANE in specification, dimensions and fit. All sound original glazing remains.

