

Ref: LBC/19/00686 – TSD20
Date: 13/10/2025



MATERIAL SAMPLES CONDITION: CONDITION 2 APPLICATION – SHIREHALL REF: LBC/2019/00686

Please find below photographs taken of the samples of materials proposed for the REPLACEMENT OF DEFECTIVE LEAD TO THE EXISTING ROOFSCAPE at the above applicant site:



Plate 1: Existing lead flashings



Plate 2: Code 4 & 6 rolled lead proposed to replace



Plates 3,4 & 5: Selection of photographs of defective lead flashings and soakers found existing (code 4 soakers existing, code 6 flashings existing).

LEAD TO BE USED TO REPLACE DEFECTIVE SECTIONS : CODE 4 OR CODE 6 ROLLED LEAD TO EXACTLY MATCH EXISTING, adding patination oils to all sections replaced.



TSD Group, 3 Parcau Road, Bridgend, CF31 4TA
www.tsdgroup.org