

By dwelling on top tier, and looking to boundary fence to the south



Existing north boundary wall on top tier and looking down garden



Views from top tier over boundary wall



Middle tier



Middle tier



Views from bottom of garden up to the dwelling



Photo taken of middle tier- photos shows existing wall on the side boundary. tier brought down one breeze block, not been built up



Bottom of garden and relationship with rear neighbour to the left



Photo down side alley of house
toward garden



Photos of neighbour to north, have a
raised patio adjacent to side boundary

