

PLA0090624



LEGEND(Representative of most common features)

	Foul chamber		Outfall
	Surface water chamber		Lampole
	Combined chamber		Storm Overflow
	Combined sewer overflow		Rising main
	Special purpose chamber		Gravity sewer
	Private sewer		Private sewer subject to Sect. 104 adoption agreement
	Pumping station		Private Sewer Transfer
	NB: Sewer symbol colour indicates the type.		Lateral Drain
	RED - Combined		Inspection Chamber
	GREEN - Surface Water		
	BROWN - Foul		
	Purple - Former S24 sewers (for indicative purposes only)		

Notes:

Whilst every reasonable effort has been taken to correctly record the pipe material of DCWW assets, there is a possibility that in some cases pipe material (other than Asbestos Cement or Pitch Fibre) may be found to be asbestos cement (AC) or Pitch Fibre (PF). It is therefore advisable that the possible presence of AC or PF pipes be anticipated and considered as part of any risk assessment prior to excavation.

Dŵr Cymru Cyllyngrdy (the Company) gives this information as to the position of its underground apparatus by way of general guidance only and on the understanding that it is based on the best information available and no warranty as to its correctness is relied upon in the event of excavations or other works made in the vicinity of the Company's apparatus. The user of this information is advised to carry out any excavations made with care and to consult the Company for further information. This information is given in accordance with the requirements of sections 105 and 106 of the Water Industry Act 1991 which in turn opens the best information available and, in particular, but not limited to the Company's responsibility, it would be noted that the records that are available to the Company may not disclose the existence of a water main, service pipe, sewer, lateral drain or other underground apparatus and any excavation should be made with care and to consult the Company for further information. The user of this information is advised to carry out any excavations made with care and to consult the Company for further information. The user of this information is advised to carry out any excavations made with care and to consult the Company for further information.

Service pipes are not generally shown but their presence should be anticipated.

**EXACT LOCATIONS OF ALL APPARATUS
TO BE DETERMINED ON SITE.**

Reproduced by permission of the Ordnance Survey on behalf of
HMSSO. © Crown copyright and database right 2017.
All rights reserved.
Ordnance Survey Licence number 100019534

Map Ref: 330811,188085
Map scale: 1:444
Printed by: Carys Barwell
Printed on: 29 Oct 2025

