

HERBERT ROAD, NEWPORT

Site Investigation Reports

	Phase 1	Phase 2A	Phase 2B	Phase 2C	Phase 2D
Site investigation report March 2013		X	X	X	X
Remediation Strategy August 2015	X	X	X	X	X
Site investigation Report Phase 1 February 2017	X				
Site investigation report Phase 2, July 2018		X			
Site investigation report phase 3 (North) July 2018					
Chemical Testing report stockpile August 2015		X	X	X	X
Letter to NCC on Upfilling December 2015		X	X	X	X
Groundwater Monitoring Letter August 2016		X	X	X	X
Groundwater Monitoring results Summary 2016		X	X	X	X
Preliminary Interim Earthworks report June 2016		X	X	X	X
Letter Piling Mat Phase 1 August 2017	X				
Letter Piling Mat Main site August 2017		X	X	X	X
Earthworks Validation Report October 2017		X	X	X	X
Earthworks Validation Report July 2018		X	X	X	X
Settlement Report August 2018		X	X	X	X
Remediation Report November 2009					
Remediation Report Appendix A November 2009					
Sampling testing of engineer fill September 2016		X	X	X	X
Imported Fill Validation report September 2016		X	X	X	X
Imported Fill validation report October 2016		X	X	X	X
Imported soil validation report December 2016		X	X	X	X
Imported Soil validation report July 2018	X				
NHBC Letter Capping Layer July 2020			X	X	X
Imported Soil validation report October 2020		X			
Imported Soil validation report November 2020			X		
Gas Letter Phase 1 June 2017	X				
Ground Gas Verification report February 2019			X	X	X
Ground Gas Validation report September 2020			X	X	X

Phase 3A	Phase 3B	Phase 3C	Phase 3D	Phase 3E
X	X	X	X	X
X	X	X	X	X
X	X			
		X	X	X
		X	X	X
X	X	X	X	X
X	X	X	X	X
		X	X	X
		X	X	X
		X	X	X
		X	X	X
X	X			
X	X			
		X	X	X
		X	X	X
		X	X	X
		X	X	X
		X	X	X
		X	X	X