

Test Records

Tests performed by: G A Fire
1 Brynderi Terrace Treowen
Newport, NP113DJ
gafireuk@outlook.com



Lights Window - Living Room

Asset ID	19	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 MΩ	19.99 MΩ	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Lights Window - Living Room

Asset ID	18	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 MΩ	19.99 MΩ	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Wi-Fi Booster - Living Room

Asset ID	17	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 MΩ	19.99 MΩ	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Extension Lead - Living Room

Asset ID	16	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Lead

Test name	Limit	Measured value	Status
Visual			Pass
Polarity		Good	Pass
Insulation	1 MΩ	19.99 MΩ	Pass
Continuity	0.1 Ω	0.05 Ω	Pass

No photo available

Overall status: Pass

Extension Lead - Living Room

Asset ID	15	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Lead

Test name	Limit	Measured value	Status
Visual			Pass
Polarity		Good	Pass
Insulation	1 MΩ	19.99 MΩ	Pass
Continuity	0.1 Ω	0.05 Ω	Pass

No photo available

Overall status: Pass



Wi-Fi Bt - Living Room

Asset ID	14	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 MΩ	19.99 MΩ	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Tv Box - Living Room

Asset ID	13	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 MΩ	19.99 MΩ	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Tv - Living Room

Asset ID	12	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 MΩ	19.99 MΩ	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Extension Lead - Kitchen

Asset ID	11	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Lead

Test name	Limit	Measured value	Status
Visual			Pass
Polarity		Good	Pass
Insulation	1 MΩ	19.99 MΩ	Pass
Continuity	0.1 Ω	0.06 Ω	Pass

No photo available

Overall status: Pass

Extension Lead - Kitchen

Asset ID	10	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Lead

Test name	Limit	Measured value	Status
Visual			Pass
Polarity		Good	Pass
Insulation	1 MΩ	19.99 MΩ	Pass
Continuity	0.1 Ω	0.09 Ω	Pass

No photo available

Overall status: Pass



Tumble Dryer - Kitchen

Asset ID	09	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	0.10 Ω	Pass
Insulation	1 M Ω	19.99 M Ω	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Washing Machine - Kitchen

Asset ID	08	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	0.10 Ω	Pass
Insulation	1 M Ω	19.99 M Ω	Pass
Leakage	5 mA	3.52 mA	Pass

No photo available

Overall status: Pass

Fridge / Freezer - Kitchen

Asset ID	07	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	0.10 Ω	Pass
Insulation	1 M Ω	19.99 M Ω	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Fridge / Freezer - Kitchen

Asset ID	06	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	0.09 Ω	Pass
Insulation	1 M Ω	19.99 M Ω	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Iron - Kitchen

Asset ID	05	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	0.09 Ω	Pass
Insulation	1 M Ω	19.99 M Ω	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass



Extension Lead - Kitchen

Asset ID	04	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Lead

Test name	Limit	Measured value	Status
Visual			Pass
Polarity		Good	Pass
Insulation	1 M Ω	19.99 M Ω	Pass
Continuity	0.1 Ω	0.06 Ω	Pass

No photo available

Overall status: Pass

Toaster - Kitchen

Asset ID	03	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	0.10 Ω	Pass
Insulation	1 M Ω	19.99 M Ω	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Kettle - Kitchen

Asset ID	02	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	0.10 Ω	Pass
Insulation	1 M Ω	19.99 M Ω	Pass
Leakage	5 mA	0.10 mA	Pass

No photo available

Overall status: Pass

Microwave - Kitchen

Asset ID	01	Test date	2022/09/12
Client	Fernando Mendoza	Next visual test	2023/09/12
Site	4 Fields Road Newport	Next full test	2023/09/12

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	0.05 Ω	Pass
Insulation	1 M Ω	19.99 M Ω	Pass
Leakage	5 mA	0.25 mA	Pass

No photo available

Overall status: Pass

END OF RESULTS