






Side 1
East




Actual artworkable space



Main Entrance
East



Potential Structural
Frame behind window may mean
cannot be wrapped



North
Toilets Block of visibility through window