H6
H11
5
7
9
10
14
13
15
4
H16*
H3
Package sewage treatment plant & drainage field
2
1
17
Beech
Protected by TPO
20
21
Inspection chamber for future connection to main house
18*
Existing parking
Service routes - fresh water and electrical supply
Approximate location of new drainage run
Existing shared septic tank - to be disconnected
26
Griselinia
29
27
28
Griselinia

N
W
E
S
5m
10m

Symbol Guide

Root Protection Area
Canopy Spread
Tree Position, (colour represents retention category)
Tag Number

BS5837:2012 - Tree Category

- Category A Trees High Quality
- Category C Trees Low Quality
- Category B Trees Moderate Quality
- Category U Trees Poor Quality/Remove
- 'No Dig' Cellular Confinement System
- New Foul Drainage
- Service Runs - Fresh Water & Electrical

Approximate sweep of shade cast by trees in midsummer, plotted as per description in BS5837: 2012

"An indication of potential direct obstruction of sunlight can be illustrated by plotting a segment, with a radius from the centre of the stem equal to the height of the tree, drawn from due north-west to due east, indicating the shadow pattern through the main part of the day."

NOTE: Tree/group numbers marked have approximate locations.

JACK PINE ARBORICULTURAL CONSULTANCY
122 Bloomfield Road
Brislington, Bristol BS4 3RD
Tel & Fax: 0117 377 8432
Mobile: 07974 398406
Email: steve@jack-pine.co.uk
Web: www.jack-pine.co.uk

Project Name:
The Grove, Penhow

Drawing Title:
Shade Plan

Drawing Number:
251215-TG-SP-Rev A-NB

Client:
Will Laws

Date:
December 2025

Scale:
1:200 @ A2