

CONSERVATION WORKS RECORDING – BEGINNING OF WORKS:




Plates 1-9: Survey of chimney cappings carried out

CONSERVATION WORKS RECORDING – BEGINNING OF WORKS:



Plates 10-15: Drone survey of the roof completed

CONSERVATION WORKS RECORDING – BEGINNING OF WORKS:**Plates 16-20: Completed scaffolding erection and wrapping for beginning of works****Plates 21-24: Scaffolding tied to tying eyes fitted to mortar joints**

CONSERVATION WORKS RECORDING – BEGINNING OF WORKS:



Plates 25-32: Survey of exterior stone works carried out

CONSERVATION WORKS RECORDING – BEGINNING OF WORKS:



Plates 33-42: Survey of exterior joinery carried out, work started cutting out by hand rotted joinery to third floor windows

CONSERVATION WORKS RECORDING – BEGINNING OF WORKS:



Plates 43-46: Survey of exterior joinery carried out, work started cutting out by hand rotted joinery to third floor windows

END RECORDING TSD25/04