





Intégral Géotechnique

General


- Specified Site
- Specified Buffer(s)
- Bearing Reference Point

Estimated Soil Chemistry Arsenic

Arsenic Concentrations mg/kg



Estimated Soil Chemistry Arsenic - Slice A



Order Details


Order Details: 284647269_1_1
Customer Ref: 12923/LP
National Grid Reference: 331850, 187530
Slice: A
Site Area (Ha): 1.09
Search Buffer (m): 1000

Site Details

Usk Way, Newport, NP20 2DZ

Landmark
INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk




Intégral Géotechnique

General


- Specified Site
- Specified Buffer(s)
- Bearing Reference Point

Estimated Soil Chemistry Cadmium

Cadmium Concentrations mg/kg



Estimated Soil Chemistry Cadmium - Slice A



Order Details


Order Details: 284647269_1_1
Customer Ref: 12923/LP
National Grid Reference: 331850, 187530
Slice: A
Site Area (Ha): 1.09
Search Buffer (m): 1000

Site Details

Usk Way, Newport, NP20 2DZ

Landmark
INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk




Intégral Géotechnique

General


- Specified Site
- Specified Buffer(s)
- Bearing Reference Point

Estimated Soil Chemistry Chromium

Chromium Concentrations mg/kg



Estimated Soil Chemistry Chromium - Slice A



Order Details

Order Details: 284647269_1_1
Customer Ref: 12923/LP
National Grid Reference: 331850, 187530
Slice: A
Site Area (Ha): 1.09
Search Buffer (m): 1000

Site Details

Usk Way, Newport, NP20 2DZ

Landmark
INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk