

Ref: LBC/19/00686 – TSD05

Date: 20/08/2025

MATERIAL SAMPLES CONDITION: CONDITION 2 APPLICATION – SHIREHALL REF: LBC/2019/00686

Please find below photographs taken of the samples of materials proposed for the CRACK REPAIRS TO STONES of the grins hill / witton fell (buff sandstone colour) on all facades at the above applicant site:



Plate 1: Existing stone face delaminations



Plate 2: Trial sections of stone stabilisation / shelter
(Apply behind delaminations and to all cleaved edges to re-bond. NHL 3.5; washed sharpsand; Natural goat hair 1:3:1 ratio)

Cleaved and delaminated Buff sandstones faces (all elevations) of Shirehall repaired using stone stabilising lime mortars / sheltercoats methods utilising Lime mortar mix - NHL 3.5; washed sharpsand; Natural goat hair 1:3:1 ratio