

Ref: LBC/19/00686 – TSD17

Date: 10/10/2025

## **MATERIAL SAMPLES CONDITION: CONDITION 2 APPLICATION – SHIREHALL REF: LBC/2019/00686**

Please find below photographs taken of the samples of materials proposed for the REPLACEMENT OF EXISTING LIME MORTAR EDGE SEALS TO WINDOWS WITHIN STONE REVEALS to the facades at the above applicant site:



Plate 1: Defective Lime edge seals carefully removed



Plate 2: New lime mortar edge seal installed



Plates 3,4 & 5: Selection of windows to front façade (all windows within stone reveals to receive) having renewed lime edge seals installed. Lime mortar mix proposed: 3.5NHL; Washed sharpsand; Goat Hair natural; Ratio: 1:3:1. (matched closely to existing).